FIG. 1




FIG. 2




FIG. 3





FIG. 4



(

FIG. 5





FIG. 6



7/18

FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13





FIG. 14



						1002) 				71003					
			LOCATION IDENTIFICATION NUMBER WITHIN SERVICE AREA	LA-1	LA-2	•	1005	Location identification Number within service area	LA-3	LA-2	• •		Location identification number within service area	LA-2	LA-3	•
FIG. 15	1001	HLR	¥	2	ω.		HLR FOR PHS TERMINAL	IMT SUBSCRIBER'S NUMBER	09037373	0904848484	•	HLR FOR PDC TERMINAL	IMT SUBSCRIBER'S NUMBER	0905959595	0903737373	•
			SUBSCRIBER'S NUMBER	09015151515	09026262626	• •	II	SUBSCRIBER'S NUMBER	07012345678	07012121212		王	SUBSCRIBER'S NUMBER	86868686060	09087654321	• •
			z	-	2			z	•	2			z	-	2	

FIG. 16

1104	LOCATION IDENTIFICATION NUMBER WITHIN SERVICE AREA	PLA-1	PLA-2	PLA-3	PLA-2	• •	_	••
1103	NETWORK IDENTIFICATION LONDINGER WITHIN SERVICE NAMES	1		1			ITM2000	•
1102	SUBSCRIBER'S NUMBER	070131313	070242424	07035353535	070464646		07012345678	
	Z	-	5	က	4		C	
				13	-J	!	1105	

FIG. 17




FIG. 18

